

Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744
Supplement No. 1

AFM Supplement to
Cessna Citation Model 560 AFM
STC No. ST00892LA

**FAA APPROVED
AIRPLANE FLIGHT MANUAL SUPPLEMENT
TO THE
CESSNA CITATION 560
AIRPLANE FLIGHT MANUAL**


STC NO. ST00892LA

INSTALLATION OF EMERGENCY VISION ASSURANCE SYSTEM

This supplement must be attached to the FAA Approved Airplane Flight Manual, dated 27 May 1994 or later approved revision when the airplane is modified by the installation of the Vision Safe Corp. Emergency Vision Assurance System in accordance with STC No. ST00892LA.

The information contained herein supplements or supersedes the basic manual only in those areas listed herein. For limitations, procedures, and performance information not contained in this supplement, consult the basic Airplane Flight Manual.

FAA Approved



Manager, Flight Test Branch, ANM-160L
Federal Aviation Administration
Los Angeles Aircraft Certification Office
Transport Airplane Directorate

Date: December 14, 1999

Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744
Supplement No. 1

AFM Supplement to
Cessna Citation Model 560 AFM
STC No. ST00892LA

LOG OF PAGES

REV. NO.	PAGE NO.	PAGE DATE	DESCRIPTION	FAA APPROVAL
ORIGINAL	TITLE LOG i CONTENTS 1 & 2	12/14/99	COMPLETE SUPPLEMENT	 Manager, Flight Test Branch, ANM-160L Federal Aviation Administration Los Angeles Aircraft Certification Office Transport Airplane Directorate Date: <u>December 14, 1999</u>

Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744
Supplement No. 1

AFM Supplement to
Cessna Citation Model 560 AFM
STC No. ST00892LA

TABLE OF CONTENTS

SECTION	TITLE	PAGE
1	LIMITATIONS	1
2	EMERGENCY PROCEDURES	2

FAA Approved Date: December 14, 1999

Contents

Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744
Supplement No. 1

AFM Supplement to
Cessna Citation 560 AFM
STC No. ST00892LA

Section No. 1

Limitations

Emergency Vision Assurance System

1. **No new limitations.**

Page No. 1

FAA Approved Date: _____

Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744
Supplement No. 1

AFM Supplement to
Cessna Citation Model 560 AFM
STC No. ST00892LA

Section No. VI

Emergency Procedures

Emergency Vision Assurance System

1. In the event of smoke in the cockpit, complete the AFM Emergency Procedures.
2. After completion of Emergency Procedures, implement EVAS to the point of placing the IVU on the Glare Shield.
3. If smoke accumulation threatens vision, activate EVAS.