

VISIONSAFE
CORPORATION

**EVAS Service Policy and Price Sheet
Effective June 1, 2009**

1. Biennial Inspection Service - up to 3 months after the Base Service Date as shown on the face of the EVAS unit
\$600 service fee.
2. Re-set Base Date – unit received for Biennial Inspection service 4-12 months after the Base Service Date as shown on the face of the EVAS unit
\$180 service fee, in addition to Biennial Inspection fee
Warranty is Void for EVAS Units received 4-12 months after the Base Service Date as shown on the face of the EVAS unit.
3. > 12 months past due, liquid contamination or major damage to unit - replace multiple parts and perform Biennial Inspection
\$3000 service fee
If unit is not serviceable, it will be returned to owner unserviced, at no charge
4. 120 Month Rebuild – as a minimum, replace Final Power Unit Assembly, IVU, and Battery Pack. Other parts may also be replaced as needed, to conform to current configuration.
\$6000 service fee

Other fees...

5. Hardware & Parts replaced due to customer damage
\$25.00 - \$300.00 Quote provided upon customer request.
6. IVU replaced due to customer damage
\$900